



**NOTES:**

1. It is **ESSENTIAL** that there are no cable connections to pins 1 and 5. If four conductor cable is used for the four middle connections then cut the connection to pin 5 at **BOTH** ends.  
If six conductor cable is used cut the connections to pins 1 and 5 at **BOTH** ends.
2. Note that the connections to pins 2 and 3 must be crossed at one end.

TITLE: CLEARNAV TO VARIO SERIAL CABLE	DATE: 30th Mar 2013
DRAWN BY: Angus Raby Dwg No: CN0001	PAGE: 1/1
REVISION: 1	